

# HAYAT KURTARAN KURALLARIMIZ



1

Güvensiz bir durum ya da davranışla karşılaştığında çalışmayı durdur.



2

İş tanımın haricindeki işlere müdahale etme.



3

Her zaman işe uygun ekipman, el aleti ve işin risklerine uygun Kişisel Koruyucu Ekipman kullan.



4

Makine emniyet sistemlerini (Emniyet kapısı, emniyet kilidi vb.) devre dışı bırakma. Faal ve aktif olduğundan emin ol.



5

Hareketli ekipmana dokunma, tehlikeli alanlara el/kol/vücudunu sokma ve etki alanına girme.



6

Yük kaldırma işlerinin, uygun iş makineleriyle, yetkin ekip tarafından yapıldığından emin ol.



7

Forklift ve araçlarda emniyet kemerini bağla, hız kurallarına uy.



8

Bakım faaliyetlerinde her zaman enerji (elektrik, mekanik, hidrolik vb.) izolasyonunun yapıldığından emin ol.



9

Gerektiğinde çalışma izni al. Üretim sahalarında veya depolarda ateşli iş yapma, alternatif yöntemleri kullan.



10

Uykusuz, alkollü veya ilaç etkisindeyken araç /ekipman kullanma, iş yerine gelme.



11

Çalışırken cep telefonu kullanma.



12

Belirlenmiş alanlar dışında sigara içme.

# LIFE-SAVING RULES



1

Stop working when you observe an unsafe act and condition.



2

Do not perform any work not stated in your job description



3

Use equipment and hand tools suitable for your tasks and use appropriate Personal Protective Equipment for the risks involved in your tasks at all times.



4

Never disable the safety systems (safety switch, safety door, safety fences, etc.) of the machines. Be sure they are in good condition and active.



5

Do not touch any moving equipment; do not put your hand, arm or body in a dangerous area; do not step in moving equipment's working zone/area.



6

Be sure that loads to be lifted by authorized teams using appropriate /tested equipment



7

Fasten your seat belt onboard forklifts and motor vehicles, follow the specified speed limits.



8

Be sure to electrical/mechanical/hydraulic/gravity etc.. isolation before starting to perform any maintenance work.



9

Obtain a work permit where necessary. Do not perform any hot work in the production areas or warehouses, use alternative methods.



10

Do not drive any vehicle, do not use any equipment, or come to work if you are sleepless or under the influence of alcohol or a drug/medication.



11

Do not use cell phone while working.



12

Smoke only in the allocated smoking zones.